

Six Sigma

Advanced Tools for Black Belts and Master Black Belts

Loon Ching Tang

National University of Singapore, Singapore

Thong Ngee Goh

National University of Singapore, Singapore

Hong See Yam

Seagate Technology International Singapore

Timothy Yoap

Flextronics International, Singapore

• HOCHSCHULE
LIECHTENSTEIN
Bibliothek



John Wiley & Sons, Ltd

Contents

| | |
|--------------|----|
| Preface..... | xi |
|--------------|----|

f **PART A: SIX SIGMA: PAST, PRESENT AND FUTURE**

| | |
|---|-----------|
| 1 Six Sigma: A Preamble..... | 3 |
| <i>H. S. Yam</i> | |
| 1.1 Introduction..... | 3 |
| 1.2 Six Sigma Roadmap: DMAIC..... | 4 |
| 1.3 Six Sigma Organization..... | 7 |
| 1.4 Six Sigma Training..... | 8 |
| 1.5 Six Sigma Projects..... | 10 |
| 1.6 Conclusion..... | 17 |
| References..... | 17 |
| 2 A Strategic Assessment of Six Sigma..... | 19 |
| <i>T. N. Goh</i> | |
| 2.1 Introduction..... | 19 |
| 2.2 Six Sigma Framework..... | 20 |
| 2.3 Six Sigma Features..... | 21 |
| 2.4 Six Sigma: Contrasts and Potential..... | 22 |
| 2.5 Six Sigma: Inherent Limitations..... | 23 |
| 2.6 Six Sigma in the Knowledge Economy..... | 25 |
| 2.7 Six Sigma: Improving the Paradigm..... | 27 |
| References..... | 28 |
| 3 Six Sigma SWOT..... | 31 |
| <i>T. N. Goh and L. C. Tang</i> | |
| 3.1 Introduction..... | 31 |
| 3.2 Outline of Six Sigma..... | 32 |
| 3.3 SWOT Analysis of Six Sigma..... | 32 |
| 3.4 Further Thoughts..... | 37 |
| References..... | 39 |

| | | |
|------------------------------|---|------------|
| 4 | The Essence of Design for Six Sigma..... | 41 |
| | <i>L. C. Tang</i> | |
| 4.1 | Introduction..... | 41 |
| 4.2 | The IDOV Roadmap..... | 42 |
| 4.3 | The Future..... | 48 |
| | References..... | 48 |
| 5 | Fortifying Six Sigma with OR/MS Tools..... | 49 |
| | <i>I. C. Tang, T. N. Goh and S. W. Lam</i> | |
| 5.1 | Introduction..... | 49 |
| 5.2 | Integration of OR/MS into Six Sigma Deployment..... | 50 |
| 5.3 | A New Roadmap for Six Sigma Black Belt Training..... | 52 |
| 5.4 | Case Study: Manpower Resource Planning..... | 58 |
| 5.5 | Conclusions..... | 68 |
| | References..... | 68 |
| PART B: MEASURE PHASE | | |
| 6 | Process Variations and Their Estimates..... | 73 |
| | <i>I. C. Tang and H. S. Yam</i> | |
| 6.1 | Introduction..... | 73 |
| 6.2 | Process Variability..... | 76 |
| 6.3 | Nested Design..... | 79 |
| | References..... | 83 |
| 7 | Fishbone Diagrams vs. Mind Maps..... | 85 |
| | <i>Timothy Yoap</i> | |
| 7.1 | Introduction..... | 85 |
| 7.2 | The Mind Map Step by Step..... | 86 |
| 7.3 | Comparison between Fishbone Diagrams and Mind Maps..... | 87 |
| 7.4 | Conclusion and Recommendations..... | 91 |
| | References..... | 91 |
| 8 | Current and Future Reality Trees..... | 93 |
| | <i>Timothy Yoap</i> | |
| 8.1 | Introduction..... | 93 |
| 8.2 | Current Reality Tree..... | 94 |
| 8.3 | Future Reality Tree (FRT)..... | 97 |
| 8.4 | Comparison with Current Six Sigma Tools..... | 101 |
| 8.5 | Conclusion and Recommendations..... | 105 |
| | References..... | 105 |
| 9 | Computing Process Capability Indices for Nonnormal Data; A Review and Comparative Study..... | 107 |
| | <i>L. C. Tang, S. E. Than and B. W. Ang</i> | |
| 9.1 | Introduction..... | 107 |
| 9.2 | Surrogate PCIs for Nonnormal Data..... | 108 |

| | | |
|-----------------------------|--|------------|
| 9.3 | Simulation Study..... | 113 |
| 9.4 | Discussion of Simulation Results..... | 127 |
| 9.5 | Conclusion..... | 128 |
| | References..... | 129 |
| 10 | Process Capability Analysis for Non-Normal Data with MINITAB | 131 |
| | <i>Timothy Yoap</i> | |
| 10.1 | Introduction..... | 131 |
| 10.2 | Illustration of the Two Methodologies Using a Case Study Data Set... | 132 |
| 10.3 | A Further Case Study..... | 141 |
| 10.4 | Monte Carlo Simulation..... | 145 |
| 10.5 | Summary..... | 149 |
| | References..... | 149 |
| PARTC: ANALYZE PHASE | | |
| 11 | Goodness-of-Fit Tests for Normality | 153 |
| | <i>L. C. Tang and S. W. Lam</i> | |
| 11.1 | Introduction..... | 153 |
| 11.2 | Underlying Principles of Goodness-of-Fit Tests..... | 154 |
| 11.3 | Pearson Chi-Square Test..... | 155 |
| 11.4 | Empirical Distribution Function Based Approaches..... | 157 |
| 11.5 | Regression-Based Approaches..... | 163 |
| 11.6 | Fisher's Cumulant Tests..... | 167 |
| 11.7 | Conclusion..... | 170 |
| | References..... | 170 |
| 12 | Introduction to the Analysis of Categorical Data | 171 |
| | <i>L. C. Tang and S. W. Lam</i> | |
| 12.1 | Introduction..... | 171 |
| 12.2 | Contingency Table Approach..... | 173 |
| 12.3 | Case Study..... | 176 |
| 12.4 | Logistic Regression Approach..... | 181 |
| 12.5 | Conclusion..... | 193 |
| | References..... | 193 |
| 13 | A Graphical Approach to Obtaining Confidence Limits of C_p^* | 195 |
| | <i>L. C. Tang, S. E. Than and B. W. Ang</i> | |
| 13.1 | Introduction..... | 196 |
| 13.2 | Graphing C_p , k and p | 197 |
| 13.3 | Confidence Limits for k | 199 |
| 13.4 | Confidence Limits For C^{\wedge} | 201 |
| 13.5 | A Simulation Study..... | 203 |
| 13.6 | Illustrative Examples..... | 206 |
| 13.7 | Comparison with Bootstrap Confidence Limits..... | 207 |
| 13.8 | Conclusions..... | 209 |
| | References..... | 210 |

| | | |
|-----------------------------|--|------------|
| 14 | Data Transformation for Geometrically Distributed Quality Characteristics | 211 |
| | <i>T. N. Goh, M. Xie and X. Y. Tang</i> | |
| 14.1 | Introduction..... | 211 |
| 14.2 | Problems of Three-Sigma Limits for the G Chart..... | 212 |
| 14.3 | Some Possible Transformations..... | 213 |
| 14.4 | Some Numerical Comparisons..... | 216 |
| 14.5 | Sensitivity Analysis of the Q Transformation..... | 219 |
| 14.6 | Discussion..... | 221 |
| | References..... | 221 |
| 15 | Development of A Moisture Soak Model For Surface Mounted Devices | 223 |
| | <i>L. C. Tang and S. H. Ong</i> | |
| 15.1 | Introduction..... | 223 |
| 15.2 | Experimental Procedure and Results..... | 225 |
| 15.3 | Moisture Soak Model..... | 227 |
| 15.4 | Discussion..... | 234 |
| | References..... | 236 |
| PARTD: IMPROVE PHASE | | |
| 16 | A Glossary for Design of Experiments with Examples | 239 |
| | <i>H. S. Yam</i> | |
| 16.1 | Factorial Designs..... | 239 |
| 16.2 | Analysis of Factorial Designs..... | 242 |
| 16.3 | Residual Analysis..... | 243 |
| 16.4 | Types of Factorial Experiments..... | 244 |
| 16.5 | Fractional Factorial Designs..... | 246 |
| 16.6 | Robust Design..... | 250 |
| 17 | Some Strategies for Experimentation under Operational Constraints . . . | 257 |
| | <i>T. N. Goh</i> | |
| 17.1 | Introduction..... | 257 |
| 17.2 | Handling Insufficient Data..... | 258 |
| 17.3 | Infeasible Conditions..... | 258 |
| 17.4 | Variants of Taguchi Orthogonal Arrays..... | 260 |
| 17.5 | Incomplete Experimental Data..... | 262 |
| 17.6 | Accuracy of Lean Design Analysis..... | 262 |
| 17.7 | A Numerical Illustration..... | 263 |
| 17.8 | Concluding Remarks..... | 264 |
| | References..... | 265 |
| 18 | Taguchi Methods: Some Technical, Cultural and Pedagogical Perspectives | 267 |
| | <i>T. N. Goh</i> | |
| 18.1 | Introduction..... | 268 |

| | | |
|--------------------------------------|--|------------|
| 18.2 | General Approaches to Quality..... | 268 |
| 18.3 | Stages in Statistical Applications..... | 269 |
| 18.4 | The Taguchi Approach..... | 272 |
| 18.5 | Taguchi's 'Statistical Engineering'..... * <i>&imu.</i> | 273 |
| 18.6 | Cultural Insights..... | 282 |
| 18.7 | Training and Learning..... | 286 |
| 18.8 | Concluding Remarks..... | 291 |
| 18.9 | Epilogue..... | 292 |
| | References..... | 293 |
| 19 | Economical Experimentation via 'Lean Design'..... | 297 |
| | <i>T. N. Goh</i> | |
| 19.1 | Introduction..... | 297 |
| 19.2 | Two Established Approaches..... | 298 |
| 19.3 | Rationale of Lean Design..... | 298 |
| 19.4 | Potential of Lean Design..... | 299 |
| 19.5 | Illustrative Example..... | 302 |
| 19.6 | Possible Applications..... | 303 |
| 19.7 | Concluding Remarks..... | 305 |
| | References..... | 306 |
| 20 | A Unified Approach for Dual Response Surface Optimization..... | 307 |
| | <i>L. C. Tang and K. Xu</i> | |
| 20.1 | Introduction..... | 307 |
| 20.2 | Review of Existing Techniques for Dual Response Surface Optimization..... | 308 |
| 20.3 | Example 1..... | 314 |
| 20.4 | Example 2..... | 319 |
| 20.5 | Conclusions..... | 320 |
| | References..... | 322 |
| PART E: CONTROL PHASE | | |
| 21 | Establishing Cumulative Conformance Count Charts..... | 325 |
| | <i>L. C. Tang and W. T. Cheong</i> | |
| 21.1 | Introduction..... | 325 |
| 21.2 | Basic Properties of the CCC Chart..... | 326 |
| 21.3 | CCC Scheme with Estimated Parameter..... | 327 |
| 21.4 | Constructing A CCC Chart..... | 330 |
| 21.5 | Numerical Examples..... | 336 |
| 21.6 | Conclusion..... | 339 |
| | References..... | 340 |
| 22 | Simultaneous Monitoring of the Mean, Variance and Autocorrelation Structure of Serially Correlated Processes..... | 343 |
| | <i>O. O. Atienza and L. C. Tang</i> | |
| 22.1 | Introduction..... | 344 |

22.2 The Proposed Approach..... 345

22.3 ARL Performance..... 346

22.4 Numerical Example..... 349

22.5 Conclusion..... 351

References..... 352

23 Statistical Process Control for Autocorrelated Processes: A Survey and An Innovative Approach..... 353

L. C. Tang and O. O. Atienza

23.1 Introduction..... 353

23.2 Detecting Outliers and Level Shifts..... 355

23.3 Behavior of $A_{LS}($ 358

23.4 Proposed Monitoring Procedure..... 363

23.5 Conclusions..... 366

References..... 368

24 Cumulative Sum Charts with Fast Initial Response..... 371

L. C. Tang and O. O. Atienza

24.1 Introduction..... 371

24.2 Fast Initial Response..... 374

24.3 Conclusions..... 379

References..... 379

25 CUSUM and Backward CUSUM for Autocorrelated Observations. 381

L. C. Tang and O. O. Atienza

25.1 Introduction..... 381

25.2 Backward CUSUM..... 382

25.3 Symmetric Cumulative Sum Schemes..... 387

25.4 CUSUM Scheme for Autocorrelated Observations..... 391

25.5 Conclusion..... 404

References..... 405

Index..... 407